

General Environmental Incident Summary

Incident: 6988

Notice: 2/18/2019

Occurred: 2/16/2019 1830

DEM Incident No:

No Further Action:

Responsible Party: Schlumberger

County: Williams

Twp Rng Sec Qtr: 156 101 10

Lat Long + Method: 48.34349 -103.66320 Interpolation from map

Location Description: Hwy 2, Left (East) past MM32 to Hwy 85, Left (North) .2 Miles to 64th St. Left (West) 1.7 Miles, Right into Location.

Submitted By Info: Ivor Filiaga
5922 Dakota Parkway West
Williston ND

Received By Info:

Contact Info:
5922 Dsakota Parkway West
Williston ND 58801

Affected Medium: 04 - water and soil

Near. Occupied Bldg:

Type of Incident: Pill Skid Valve Failure

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Fresh Water

Volume of Release:

Duration of Release:

Agriculture Related: No

EPA Extremely Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Approximately 10 barrels of fresh water leaked onto the ground due to a Pill Skid Valve failure

Risk Evaluation:

N/A

Potential Env. Impacts:

N/A

Action Taken/Planned:

The spill was contained and immediately sucked up with a suck truck that is staged on location

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 2/18/2019 **Status:** Reviewed - Follow-up Required

Author: DeVries, Taylor

Notes:

According to incident report, the release was not contained. Further follow-up is needed.

Updated Volume: None at the time of this update

Date: 2/26/2019 **Status:** Inspection

Author: Kangas, Kathleen

Notes:

Onsite 2/26/2019 at 1:50pm. -2 degrees and cloudy. Spoke to company rep who confirmed that, for this spill at this work site, it was only fresh water that spilled. Appears no environmental contamination from this spill. Another reported spill also came in from this work site, report #6999.

Updated Volume: None at the time of this update