

General Information

Total Number of UST Facilities: 830

Public Record Posted Date: 10/01/2024

Total Number of USTs: 2208

Reporting Period Dates: 10/01/2023 to 09/30/2024

Summary Information For On-Site Inspections

Criteria

Number of UST Facilities Inspected: 351

Indian Lands: False

Percent Compliance: 32.53%

Summary Information For Release

Number of Confirmed UST Releases: 4

Summary Information For Release Sources and Causes

Source			Cause													
			Spill		Overfill		Phy/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	2	40.0	1	50.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	33.3
Piping	1	20.0	1	50.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Dispenser	1	20.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	33.3
STP	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Delivery Problem	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
Other	1	20.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	33.3
Totals	5	100.0	2	100.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	3	100.0

= Number of releases

% = Percent of total number of Source

Note: Release, sources and causes information are based on USTs as defined in NDAC Section 33.1-24-08-40. Source and cause data is collected from information provided through release reporting as required in NDAC Section 33.1-24-08-40. Site specific UST information on compliance and releases can be obtained upon request.