

**General Information**

Total Number of UST Facilities: 834      Public Record Posted Date: 09/30/2022  
 Total Number of USTs: 2212      Reporting Period Dates: 10/01/2021 to 09/30/2022

**Summary Information For On-Site Inspections**

**Criteria**

Number of UST Facilities Inspected: 260      Indian Lands: False  
 Percent Compliance: 47.15%

**Summary Information For Release**

Number of Confirmed UST Releases: 4

**Summary Information For Release Sources and Causes**

Source			Cause													
			Spill		Overfill		Phy/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	3	27.3	0	0.0	2	50.0	0	0.0	0	0.0	0	0.0	0	0.0	1	16.7
Piping	1	9.1	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	16.7
Dispenser	4	36.4	1	100.0	2	50.0	0	0.0	0	0.0	0	0.0	0	0.0	1	16.7
STP	1	9.1	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	16.7
Delivery Problem	1	9.1	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	16.7
Other	1	9.1	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	1	16.7
Totals	11	100.0	1	100.0	4	100.0	0	100.0	0	0.0	0	0.0	0	0.0	6	100.0

# = Number of releases  
 % = Percent of total number of Source

Note: Release, sources and causes information are based on USTs as defined in NDAC Section 33.1-24-08-40. Source and cause data is collected from information provided through release reporting as required in NDAC Section 33.1-24-08-40. Site specific UST information on compliance and releases can be obtained upon request.